Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Maintenance of toilet at J.P.Park in Ward NO.17 in RRN Zone
2	Administration Approval & Date	CE/RRN/AS/11/10-11 Dtd 23-04-2011 by CE (RRN)
3	Technical Sanction Estimate No. & Date	CE/RRNZ/TS/21/10-11 dtd:23-04-2011 by CE (RRN)
4	Estimate Amount	Rs.20.00/- Lakhs
5	Job Code No.	017-11-000042
6	P-Code	P-0974
7	Agreement No & date	EE(P)/RRN/AG No./18/2011-12 Dtd.04-05-2011
8	Work order Number & Date	EE/Proj/RRN/W.O/18/2011-12 Dtd.04-05-2011
9	Contract Amount as per Agreement	Estimated Amount +10%
10	Bill Amount	Rs.19,06,163/-
11	B.R. No. & Date	328/2012-13 dt.30-08-2013
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	516/ Pages 51519 to 51536
14	Date of Inspection	5/7/2015
15	Enclusures	1) Extract of MB No.516 Page No.51536 2) 4 Number of photos taken during inspection
16	Inspection Report	The above site was Inspected by along with the concerned officials. The measurements were checked by me and found to satisfactory

As per the records photos are enclosed please

EE (P) RR Nagara

5/7/2015

(R.Sathyanarayana)
Inspection Report officer,

Rinth

M.A.R. 57 (Rule 116)

Measurement Book

No. C/09

No. ..... From ..... To 051536 7

of work ..... Nagar Zone

of Contractor of nature of Agency .....

of commencement of work Op Park Main Road .....

Full description, etc, of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement	Reference to last Measurement
	3	4	5	6	7	8	8
Main Gate Animal 2 Statue Ticket counter Gate. Road. Rock garden Pathway Toilet Work Spot Musical Fountain. Pathway Pathway Toilet Work Spot Bridge. Pathway Muthyalamagam Main Road. Gate Cp Area 4 46 Pathway ASE(P)-1 2 RRN							Sanitory and above dressing in clear from plate as 80.00 N 7.5 with tal coope l machine ted. in machinery

5/7/20

Inspection of the w